

FAG 32011-X-N11CA参数

| | | | | | |
|----------|-----------------|--------|--------|-------------|-------------|
| 尺寸 | d | 55 | mm | - | |
| | D | 90 | mm | - | |
| | 2T | 46 | mm | - | |
| | 2B | 46 | mm | - | |
| | A | 11 | mm | - | |
| | $C_{a \min}$ | 4 | mm | - | |
| | $D_{a \max}$ | 83 | mm | - | |
| | $D_{a \min}$ | 81 | mm | - | |
| | $d_{a \max}$ | 63 | mm | - | |
| | $r_{3, 4 \min}$ | 1.5 | mm | - | |
| | $r_{b \max}$ | 1.5 | mm | - | |
| | 重量 | m | 1310 | g | 质量 |
| | 基本额定载荷 | C_r | 138000 | N | 基本额定动载荷, 径向 |
| C_{0r} | | 235000 | N | 基本额定静载荷, 径向 | |
| 计算系数 | e | 0.41 | | - | |
| | Y_0 | 1.62 | | - | |
| | Y_1 | 1.66 | | - | |
| | Y_2 | 2.47 | | - | |
| 疲劳极限载荷 | C_{ur} | 29000 | N | 疲劳极限载荷, 径向 | |
| 极限转速 | n_G | 7000 | r/min | 极限转速 | |
| 参考转速 | n_B | 3800 | r/min | 参考速度 | |

FAG 32011-X-N11CA图片





参考资料:<http://www.sozhou.com/p/576d62a1.html>