

FAG HCS71926-C-T-P4S参数

| | | | | |
|--------|-----------|------------|-------|-------------|
| 尺寸 | d | 130 | mm | - |
| | D | 180 | mm | - |
| | B | 24 | mm | - |
| | a | 33 | mm | - |
| | D_a H12 | 171 | mm | - |
| | d_a h12 | 139 | mm | - |
| | r_a max | 0.6 | mm | - |
| | r_{min} | 1.5 | mm | - |
| | 极限转速 | n_G Fett | 13000 | r/min |
| 疲劳极限载荷 | C_{ur} | 2140 | N | 疲劳极限载荷, 径向 |
| 重量 | m | 1760 | g | 质量 |
| 基本额定载荷 | C_r | 40500 | N | 基本额定动载荷, 径向 |
| | C_{0r} | 25500 | N | 基本额定静载荷, 径向 |

FAG HCS71926-C-T-P4S图片



