

### FAG NU1008-M1参数

参考转速	$n_B$	8900	r/min	参考速度
疲劳极限载荷	$C_{ur}$	3800	N	疲劳极限载荷，径向
尺寸	$d$	40	mm	-
	$D$	68	mm	-
	$B$	15	mm	-
	$D_1$	58.2	mm	-
	$D_{a\ max}$	63	mm	-
	$d_{a\ max}$	46	mm	-
	$d_{a\ min}$	43	mm	-
	$d_{b\ min}$	49	mm	-
	$E$	61	mm	-
	$F$	47	mm	-
	$r_{l\ min}$	0.6	mm	-
	$r_{a\ max}$	1	mm	-
	$r_{al\ max}$	0.6	mm	-
	$r_{min}$	1	mm	-
		$s$	2	mm
重量	$m$	216	g	质量
基本额定载荷	$C_r$	33500	N	基本额定动载荷，径向
	$C_{0r}$	30500	N	基本额定静载荷，径向
极限转速	$n_G$	17700	r/min	极限转速

### FAG NU1008-M1图片



参考资料:<http://www.sozhou.com/p/d4e5751e.html>

