

FAG NJ411-M1参数

参考转速	n_B	5100	r/min	参考速度
疲劳极限载荷	C_{ur}	30000	N	疲劳极限载荷，径向
尺寸	d	55	mm	-
	D	140	mm	-
	B	33	mm	-
	B_1	10	mm	-
	B_2	16.5	mm	-
	D_1	110.7	mm	-
	$D_{a\ max}$	126	mm	-
	d_1	85	mm	-
	$d_{a\ max}$	76	mm	-
	$d_{a\ min}$	69	mm	-
	$d_{c\ min}$	87	mm	-
	F	77.2	mm	-
	$r_{1\ min}$	2.1	mm	-
	$r_{a\ max}$	2.1	mm	-
	$r_{al\ max}$	2.1	mm	-
	r_{min}	2.1	mm	-
	s	3.3	mm	距离中心位置的轴向偏移
重量	m	2880	g	质量
基本额定载荷	C_r	187000	N	基本额定动载荷，径向
	C_{0r}	164000	N	基本额定静载荷，径向
极限转速	n_G	8200	r/min	极限转速

FAG NJ411-M1图片





参考资料:<http://www.sozhou.com/p/4f4e5e59.html>