

FAG NU1018-M1参数

极限转速	n_G	8400	r/min	极限转速
参考转速	n_B	4550	r/min	参考速度
疲劳极限载荷	C_{ur}	16200	N	疲劳极限载荷，径向
尺寸	d	90	mm	-
	D	140	mm	-
	B	24	mm	-
	D_1	122.9	mm	-
	$D_{a\ max}$	133	mm	-
	$d_{a\ max}$	101	mm	-
	$d_{a\ min}$	96	mm	-
	$d_{b\ min}$	106	mm	-
	E	127	mm	-
	F	103	mm	-
	$r_{1\ min}$	1.1	mm	-
	$r_{a\ max}$	1.5	mm	-
	$r_{al\ max}$	1	mm	-
	r_{min}	1.5	mm	-
		s	3	mm
重量	m	1360	g	质量
基本额定载荷	C_r	111000	N	基本额定动载荷，径向
	C_{0r}	124000	N	基本额定静载荷，径向

FAG NU1018-M1图片



参考资料:<http://www.sozhou.com/p/72745a5a.html>

